



Topcon Receiver Utility (TRU)

Release Notes

Version 3.6.1

August 2022

©Copyright Topcon Positioning Systems, Inc. 2022.

All contents in this manual are copyrighted by Topcon. All rights reserved. The information contained herein may not be used, accessed, copied, stored, displayed, sold, modified, published, or distributed, or otherwise reproduced without express written consent from Topcon.

Table of Contents

VERSION 3.6	3
FEATURES AND CHANGES.....	3

Version 3.6.1

(Release build number r169923)

Features and Changes

- GNSS FW 5.5 support
- Add IPv6 support for TCP Server/Client
- Support display of data from secondary antennas in multi-antenna receivers including real time monitoring of SV list with SNR
- Automatic mounting of Internal Media during One-File firmware update
- Provide an ability to setup current drive
- Ability to copy selected information in Receiver Info screen
- Extended IRNSS constellation support in UI and help files
- Support RINEX 3.05 version
- Support for QZSS L1C/B signal
- Extended support for BDS PRNs 59-63
- Added support BEIDOU-3 B2b signal
- Support new imode "cryp"
- Support ALRT receiver option
- Update Virtual Serial Port driver in TRU installation
- Add Topcon USB drivers to installation
- Support for jps/rD, and jps/rd messages
- Support for fractional SNR part in rS, rD, rd messages
- Added UTC time and RTC time to Receiver Info
- Support Device Instance Path along with the standard COM<N> names for serial ports
- Fixed display of modem driver information in Modems | Properties dialog
- Fixed error when installing localized version of TRU when TRU instance already opened
- Fixed timeout error when selecting "track all satellites" for BeiDou constellation.
- General User Interface improvements